



HMEC® AUTONIO™ L-R.Parts™

HMEC (CHINA) CORP.

Turbo Charger for LAND ROVER

LAND-ROVER.Parts

+86-21-60488918 F:+86-21-33250332 AutoParts@AUTONIO.com www.AUTONIO.com www.L-R.Par  
7D, 450 Fushan Rd., Pudong, Shanghai 200122, China

AUTONIO NO.	MODEL	PARTS NO.	OEM NO.	APPLICATION	ENGINE	TURBO ERP	CORE ERP
Jaguar							
HTC161263	GT1749V	728680-0012	4S7Q-6K682-EK	Ford Mondeo III/Jaguar X Type	PUMA		03001-A2427
Land Rover							
HTC161349	GT1749V	778400-0003 778400-0004 778400-0005	LR056369 LR029915 LR013202	Discovery IV TDV6	V6	03002-A0938	03001-A2552
HTC151214	GT1749V	708366-0001 708366-0002 708366-0003 708366-5005 708366-5007	7781450B 77814759 77814769	FreelanderI 2.0 TD4	M47D		03001A2418
HTC15993	GT1752V	753546-0023 753546-0014	LR006862 LR003578 6G9Q6K682CB 6G9Q6K682CA 9684856680	FreelanderII 2.2 TD4	DW12B		03001A1737
HTC151145	K04	5304-970-0065 5304-988-0115 5304-988-0069	LR021637 LR021042 LR004286 LR005954 LR006422 LR003356 LR005846 LR010188	DiscoveryIII Range Rover 2.7 TDV6	V6	03002-A0906	03001-A2529
SL151235	BV39	5439-970-0112 5439-970-0063	LR021044 LR003668 LR004038 LR008827	Range Rover 3.6 TDV8	TDV8		03001A2355
HTC08302	TB250	452055-0004	ERR4893 PM10051	Discovery Defender	2.5LD	0300-2337	03001-A1050
HTC151239	TD04L	49477-01202 49477-01203 49477-01204 49477-01213 49477-01214	LR065510 LR049592 LR038309 LR038322 LR022358	Evoque 2.2 TD4	TD4		03001A2461

HTC161332	GT1549S	452202-5004S 452202-0004 452202-0003	PMF100490 PMF100400 PMF180490	Land-Rover Freelander I 2.0 Di	TCIE		03001A2516
HTC15948	GT2052S	452239-0005 452239- 0003 452239-0006 452239-0009 452239-	LR017316 LR006595 LR005955 PMF50040 PMF000040 PMF100460	Land-Rover Dissovery 2 2.5TDI	TD5		03001A1670
HTC151023	BV39	5439-970-0064 5439-970-0113	LR021653 LR021043 LR003667 LR004037 LR008826	Range Rover 3.6	TDV8		03001-A2076